

# Pre Purchase Inspection Report

Holden Commodore SV6

Reference Number: a02fff30-bd0b-4e31-a493-9bcdf705befb



## Vehicle Information


**VIN**  
6G1EK5xxxxxxxxxx















































**Model Year**  
2007


**Odometer Reading**  
199621










**Registration Number**  
IAR003

Report Summary



| Part                               | Comments  | Rating(Out of 5)   |
|------------------------------------|---|--|
| Engine Bay Fluid Levels            | Engine oil looks good but flagging on dashboard needs replacement. Just needs to reset system                 | 4<br> <br> <br>           |
| Fluid Leaks and Residue            | No visible leak during inspection   | 4<br> <br> <br>           |
| Radiator fan, Hoses & Reservoir    |   | 4<br> <br> <br>           |
| Thermostats Housing and water pump |   | 4<br> <br> <br>          |
| Coolant condition                  |   | 4<br> <br> <br> |
| Heater hoses & heater core         | <br><a href="#">View</a> | 4<br> <br> <br> |
| A/C condenser, Compressor & lines  | Unable to determine until we fill up AC gas so that we know weather or not it's leaking                       | 0<br> <br> <br> |
| Drive belt and tensioner           | Drive belt need replacement makes noise whilst vehicle is running. Tensioner is good                          | 2<br> <br> <br> |
| Power Steering pump and hoses      |   | 4<br> <br> <br> |


| Part                                   | Comments  | Rating(Out of 5)     |
|--|---|----------------------|
| Electronic power steering              |   | 0<br>★ ★<br>★ ★<br>★ |
| Fuel pump / Fuel line / fuel injectors |   | 4<br>★ ★<br>★ ★<br>★ |
| Starter motor                          |   | 4<br>★ ★<br>★ ★<br>★ |
| Intake manifold                        |   | 4<br>★ ★<br>★ ★<br>★ |
| Turbo charger                          |   | 0<br>★ ★<br>★ ★<br>★ |
| Super Charge                           |   | 0<br>★ ★<br>★ ★<br>★ |
| Engine fuse box                        | <br><a href="#">View</a> | 4<br>★ ★<br>★ ★<br>★ |
| Washer bottle                          |   | 4<br>★ ★<br>★ ★<br>★ |
| Oil cap deposit and oil condition      |   | 4<br>★ ★<br>★ ★<br>★ |














| Part                 | Comments  | Rating(Out of 5)   |
|----------------------|---|--|
| Engine oil leak      | No visible engine oil leaks at the time of inspection   | 4<br>   |
| Engine mounts        |   | 4<br>   |
| Engine Health        |   | 4<br>   |
| Head gasket leakage  | No leakage  | 4<br>  |
| Engine / Motor Noise |   | 4<br> |
| Engine idling        |   | 3<br> |
| Ignition System      |   | 4<br> |
| ECU Scan             | No fault codes<br><div>  <a href="#">View</a> </div> | 4<br> |

## Drive Line










| Part                               | Comments | Rating (Out of 5) |
|------------------------------------|----------|-------------------|
| Gear Box / Transmission Mounts     |          | 3 ★ ★ ★ ★         |
| Clutch padle and Slave Cylinder    |          | 0 ★ ★ ★ ★         |
| Transmission oil condition         |          | 0 ★ ★ ★ ★         |
| Driveshaft and boots condition     |          | 4 ★ ★ ★ ★         |
| Front differential / Transfer case |          | 0 ★ ★ ★ ★         |
| Rear differential & Tail Shaft     |          | 0 ★ ★ ★ ★         |
| Leaf / Coil springs                |          | 4 ★ ★ ★ ★         |
| Drive line images                  |          | 0 ★ ★ ★ ★         |











































## Performance and Control

| Part                 | Comments   | Rating (Out of 5) |
|----------------------|--|-------------------|
| Exhaust              |  | 0<br>★ ★ ★ ★<br>★ |
| Tyres condition      | 60%  | 3<br>★ ★ ★ ★<br>★ |
| Brake disc condition | Front brakes needs replacement.<br>Rear not too bad<br><div>  <a href="#">View</a> </div> | 2<br>★ ★ ★ ★<br>★ |
| Front brake pads     |  | 2<br>★ ★ ★ ★<br>★ |
| Rear brake pads      |  | 3<br>★ ★ ★ ★<br>★ |

| Part                                       | Comments      | Rating (Out of 5)  |
|--|---------------|--|
| Brake master, calliper and hoses           |               | 4<br><br>  |
| Sway bar links and torsion bar             |               | 4<br><br>  |
| Steering rack / tie rod ends / Ball joints | Needs replace | 1<br><br><br> |
| Shock absorber / Struts                    |               | 3<br><br>  |
| Hub assembly / Wheel bearings              |               | 4<br><br>  |
| Suspension bushes / Control Arm bushes     |               | 3<br><br>  |


## Exterior

| Part   | Comments                        | Rating (Out of 5)  |
|--|---------------------------------|--|
| Windscreen, bonnet and bonnet struts   | Bonnet struts needs replace     | 2<br><br><br> |
| Park / low & high beam / reverse / brake / repeater / fold lenses and globes | Rear tail lights need replacing | 3<br><br><br> |
| Side mirrors   |                                 | 4<br><br><br> |

| Part                                  | Comments  | Rating<br>(Out of 5)   |
|---------------------------------------|---|--|
| Door lock and keys                    | Sometime rear doors don't lock at first lock. To lock the vehicle you will need to Lock, unlock, lock.  | 2<br> <br> <br>           |
| Glass / trim / weather seals / moulds | Front windscreen sealing needs replacement deep<br><div>   </div> <div> <a href="#">View</a> <a href="#">View</a> </div> | 2<br> <br> <br>           |
| Doors / Door seals                    |   | 3<br> <br> <br>           |
| Sunroof / Aerial / Convertible        |   | 0<br> <br> <br>       |
| Fuel cap                              |   | 4<br> <br> <br> |
| Boot / tailgate struts / Rear bumper  | Bonnet struts needs replacement   | 2<br> <br> <br> |
| Body Repairs /Panels damage           | Minor couple of dints around nothing major  | 4<br> <br> <br> |
| Rust                                  |   | 4<br> <br> <br> |

## Interior



| Part   | Comments   | Rating (Out of 5) |
|--|--|-------------------|
| Carpet condition / Door mats / pedals and dashboard                    |  | 4 ★ ★ ★ ★ ★       |
| Glove box / air vents  |  | 4 ★ ★ ★ ★ ★       |
| Roof lining / Sun roof   |  | 0 ★ ★ ★ ★ ★       |
| Sun visors / interior light/ Rear view mirror                          |  | 4 ★ ★ ★ ★ ★       |
| Comb. Switch / hazard light switch                                     |  | 4 ★ ★ ★ ★ ★       |
| Windows Operation  |  | 4 ★ ★ ★ ★ ★       |
| Front and rear wiper inserts / Washers                                 |  | 4 ★ ★ ★ ★ ★       |
| Heater operation   |  | 4 ★ ★ ★ ★ ★       |
| Air condition operation  | Air con not functioning  | 1 ★ ★ ★ ★ ★       |
| Head unit / CD player / Radio / Navigation                             |  | 4 ★ ★ ★ ★ ★       |
| Central console  |  | 4 ★ ★ ★ ★ ★       |
| Steering Wheel grip / Horn   | <br><a href="#">View</a> | 2 ★ ★ ★ ★ ★       |
| Park brake operation   |  | 4 ★ ★ ★ ★ ★       |
| Fuel gauges / temp gauges  |  | 4 ★ ★ ★ ★ ★       |
| Front and rear seats heater & operation / Seat belts / Seats condition |  | 4 ★ ★ ★ ★ ★       |
| Owner's Manual – Service Logbook                                       |  | 0 ★ ★ ★ ★ ★       |

## Road Test

| Part                            | Comments | Rating (Out of 5) |
|---------------------------------|----------|-------------------|
| Exhaust Smoke                   |          | 3 ★ ★ ★ ★ ★       |
| Engine / Motor Driving Noise    |          | 3 ★ ★ ★ ★ ★       |
| Road Handling & Wheel alignment |          | 4 ★ ★ ★ ★ ★       |

| Part                                      | Comments | Rating (Out of 5) |
|---|----------|-------------------|
| Steering vibration / Driveshaft vibration |          | 4 ★ ★ ★ ★ ★       |
| Brake (ABS) Operation                     |          | 4 ★ ★ ★ ★ ★       |
| Gearbox 4WD Hight & Low                   |          | 0 ★ ★ ★ ★ ★       |
| Gearbox Auto / Manual                     |          | 4 ★ ★ ★ ★ ★       |
| Steering and suspension Performance       |          | 4 ★ ★ ★ ★ ★       |
| Speedometer / Odometer Functionality      |          | 4 ★ ★ ★ ★ ★       |
| Trip meter cruise control                 |          | 4 ★ ★ ★ ★ ★       |
| Turbo Charger / Super Charger             |          | 0 ★ ★ ★ ★ ★       |
| Vehicle general drivability               |          | 4 ★ ★ ★ ★ ★       |
| Speed limit when tested                   | 60       | 0 ★ ★ ★ ★ ★       |

## Hybrid System Inspection

| Part                                  | Comments | Rating (Out of 5) |
|---------------------------------------|----------|-------------------|
| High-Voltage Battery                  |          | N/A               |
| Inverter                              |          | N/A               |
| Battery performance during test drive |          | N/A               |

This report is generated by

