

Pre Purchase Inspection Report

Subaru Outback

Reference Number: 9f6aceee-8262-4c71-acdc-020bcd5779d0



Vehicle Information


VIN
IAR12340IAR1234023

Model Year
2019

Odometer Reading
072728

Registration Number
IAR001

Report Summary



Ray / Inspector



Inspector's overall review





The 2019 Subaru Outback presented for inspection was found to be in excellent condition overall. The vehicle showed no mechanical faults or cosmetic concerns at the time of inspection. The engine, transmission, suspension, brakes, and electrical systems all performed as expected during our checks. Both the interior and exterior were well maintained, consistent with age and mileage. No warning lights or faults were detected. Based on our assessment, this Subaru Outback appears to have been well cared for and is in a condition that aligns with its service history and market expectations for this model.

Engine and Motor

Part	Comments	Rating (Out of 5)
Battery health & Alternation operation	<p>Battery is new</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>View</p> </div> <div style="text-align: center;">  <p>View</p> </div> <div style="text-align: center;">  <p>View</p> </div> </div>	<p>5</p> <p>★ ★ ★ ★ ★</p>



Part	Comments	Rating (Out of 5)
Engine bay fluid levels & condition / Washer bottle.	<p>Service due now. All bay fluid are in good condition</p> 	<p>5</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>
Radiator fan, Hoses, Reservoir, Thermostats housing and Water pump		<p>5</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>
Heater hoses, AC condenser, Compressor & Lines		<p>5</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>
Drive belt and tensioner		<p>5</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>
Power steering pump & hoses / Electronic power steering.		<p>0</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>
Exhaust		<p>N/A</p>

Part	Comments	Rating (Out of 5)
Fuel pump / Fuel line / fuel injectors		5 
Starter motor	 View	5 
Air intake & induction system (intake manifold, pipes, hoses, air filter housing)	 View	5 
Turbo charger / Super Charger		0 
Engine bay electrical (fuse box, relays, main wiring looms, battery terminals)	 View  View	5 
Oil cap deposit, Head gasket leakage, Oil leaks, Engine health, Ignition System	Due for service	5 

Part	Comments	Rating (Out of 5)
Engine & transmission mounts.		5 ★ ★ ★ ★ ★
Engine idling		N/A
ECU Scan	No fault codes at the time of the inspection 	5 ★ ★ ★ ★ ★

Drive Line

Part	Comments	Rating (Out of 5)
Automatic transmission / Clutch paddle and slave Cylinder		5 ★ ★ ★ ★ ★
Transmission oil condition		5 ★ ★ ★ ★ ★

Part	Comments	Rating (Out of 5)
Driveshafts / Tail shaft and Boots condition		<p>4</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>
Front / Rear Differentials		<p>5</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>
Drive line images		<p>5</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>

Performance and Control

Part	Comments	Rating (Out of 5)
Tyres, Wheels / Rims & Spare wheel / Repair kit	<p>Tyres are 50%</p> 	<p>3</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>
Braking (Discs, Pads, master, calliper, hoses)	<p>No lips nice and flat all around</p> 	<p>5</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p> <p>★</p>

Part	Comments	Rating (Out of 5)
Sway bar link / Torsion bar		5 ★ ★ ★ ★ ★
Steering rack / Tie rod ends / Ball joints		5 ★ ★ ★ ★ ★
Shock absorbers / Struts / Coil springs		5 ★ ★ ★ ★ ★
Hub assembly / Wheel bearings		5 ★ ★ ★ ★ ★
Suspension bushes / Control Arm bushes		5 ★ ★ ★ ★ ★

Exterior

Part	Comments	Rating (Out of 5)
------	----------	-------------------

Bonnet / Doors / Boot / Seals & Struts	 View	5 ★ ★ ★ ★ ★
Head lights / Taillights / Indicators		5 ★ ★ ★ ★ ★
Side mirrors / Fuel cap / Accessories & Rust		5 ★ ★ ★ ★ ★
Glass / Seals / Moulds	 View  View	5 ★ ★ ★ ★ ★
Roof / Convertible / Racks		5 ★ ★ ★ ★ ★
Front & rear wiper blades		N/A
Body Repairs /Panels damage	Nil body damage or repairs	5 ★ ★ ★ ★ ★

Interior

Part	Comments	Rating (Out of 5)
Door locks / Car keys / Service book / Owner's manual		N/A
Carpet / Floor mats / Pedals	 View  View	5 ★ ★ ★ ★ ★
Roof lining & accessories / Sunroof (Rear mirror / Sun visors / Interior Lights)		5 ★ ★ ★ ★ ★
Window / Mirrors operations.		5 ★ ★ ★ ★ ★
Air conditioning & Heater operation		5 ★ ★ ★ ★ ★
Head unit / CD player / Radio / Navigation		5 ★ ★ ★ ★ ★

Part	Comments	Rating (Outof 5)
Dashboard / Air vents / Centre Console / Glove box		5 ★ ★ ★ ★ ★
Steering wheel grip / Horn / Comb switch		5 ★ ★ ★ ★ ★
Park brake operation		5 ★ ★ ★ ★ ★
Fuel gauges / Temperature gauges		5 ★ ★ ★ ★ ★
Car seats condition & operation / Heated, cooling / Seat belts.		5 ★ ★ ★ ★ ★
Owner's Manual – Service Logbook		5 ★ ★ ★ ★ ★
Front / Rear wiper operations / Washers		N/A

Road Test

Part	Comments	Rating (Out of 5)
Exhaust smoke / Engine idling		5 ★ ★ ★ ★ ★
Engine driving noise / Driveshaft noise or vibration		5 ★ ★ ★ ★ ★
Road handling / Wheel alignment / Steering vibration		5 ★ ★ ★ ★ ★
Braking / ABS operation		5 ★ ★ ★ ★ ★
Gearbox Auto / Manual / Paddle-shift / 4WD Hight & Low / Shifting		0 ★ ★ ★ ★ ★
Steering and suspension Performance		5 ★ ★ ★ ★ ★
Speedometer / Odometer Functionality / Cruise control		5 ★ ★ ★ ★ ★

Part	Comments	Rating (Out of 5)
Turbo Charger / Super Charger / Kickdown		0 ★ ★ ★ ★ ★
Vehicle general drivability		5 ★ ★ ★ ★ ★
Speed limit when tested	70 km/h	5 ★ ★ ★ ★ ★

This report is generated by
 Instant Auto Reach